



BOSCH

Разработано для жизни



1	2	3	4	5
1607014176 / 1607031255*	1607014171 / 1607031250	1607000V37 / 1607031266	1617000525 / 1607031256	1607014145 / 1607031223

6	7	8	9	10
1617014126 / 1607031227	1619P02870 / 1607031252	1617014144 / 1607031260	1607000V53 / 1607031254	1617014135 / 1607031236

11	12	13	14	15
2610391290 / 1607031264	3607014010 / 1607031265	2604321941 / 1607031263	1617014143 / 1607031259	2604321905 / 1607031222

*обычный артикул / промо-артикул

Перфоратор (GBH)		Отбойный молоток (GSH)		Угловая шлифмашина (GWS)	
GBH 11 DE	0 611 245 703, 708	6	GSH 11 E	0 611 316 703, 708, 796	6
GBH 2-22 E	0 611 250 603, 608	4	GSH 16-28	3 611 C35 000	14
GBH 2-22 RE	0 611 250 708		GSH 16-30	3 611 C35 100	8
GBH 2-22 S	0 611 250 003		GSH 5 CE	3 611 C21 000	
GBH 2-23 RE	3 611 B50 400		GSH 5 E	0 611 318 703, 708	
GBH 2-23 REA	3 611 B50 500		Угловая шлифмашина (GWS)		
GBH 2-24 DFR	3 611 B73 000		GWS 1000	3 601 H21 003, 8R0	3
GBH 2-24D	3 611 BA0 000		GWS 1000	3 601 H28 400, 800	
GBH 2-24DF	3 611 BA0 100		GWS 10-125	3 601 H21 000, 020, 800	
GBH 2-25 DV	3 611 B67 103		GWS 10-125 C	0 601 803 703, 903	
GBH 2-26 DBR	0 611 255 503		GWS 10-125 C	0 601 702 703, 708, 773, 903	
GBH 2-26 DFR	0 611 254 703, 708	GWS 10-125 C	0 601 802 503, 508		
GBH 2-26 DRE	0 611 253 703, 708	GWS 10-125 CE	0 601 383 703		
GBH 2-26 E	0 611 251 603	GWS 10-125 CE	0 601 703 703, 708, 773		
GBH 2-26 RE	0 611 251 703, 708	GWS 10-125 CE	0 601 703 903		
GBH 2-28	3 611 B67 500	GWS 10-125 CE	0 601 803 503, 508, 573, 574, 575, 703, 708		
GBH 2-28 F	3 611 B67 600	GWS 10-125 Z	3 601 H32 000	9	
GBH 2400	0 611 253 803	GWS 10-125C	0 601 802 573, 574, 703, 708, 773		
GBH 2600	0 611 254 803	GWS 10-125CE	0 601 803 773		
GBH 3-28 DFR	3 611 B4A 000	GWS 11-125	3 601 G92 000, 0R0		
GBH 3-28 DRE	3 611 B3A 000	GWS 11-125	3 601 G9D 000		
GBH 5-40 DCE	3 611 B64 000, 001	GWS 11-125 CI	3 601 H22 000, 020		
GBH 5-40 DE	0 611 241 703, 708	GWS 11-125 CIE	3 601 H23 000, 020		
GBH 7 DE	0 611 235 703, 708	GWS 11-125 CIH	3 601 H30 100, 120, B00		
GBH 7-45 DE	0 611 235 803, 808	GWS 11-125 P	3 601 G92 200		
GBH 7-46 DE	0 611 263 703, 708	GWS 12-125	3 601 G93 000		
Шлифмашина по бетону (GBR)		GWS 12-125 CIE	3 601 G94 000	3	
GBR 15 CA	3 601 G76 000	GWS 12-125 CIEP	3 601 G94 200		
Эксцентриксовая шлифмашина (GEX)		GWS 12-125 CIEPX	3 601 G94 300		
GEX 150 TURBO	0 601 250 703, 772, 791	GWS 12-125 CIEX	3 601 G94 100		
Прямая шлифмашина (GGS)		GWS 12-125 CIP	3 601 G93 200		
GGS 28 C	3 601 B20 000	GWS 12-125 CIPX	3 601 G93 300		
GGS 28 CE	3 601 B20 100	GWS 12-125 CIX	3 601 G93 100		
GGS 28 LC	3 601 B21 000	GWS 13-125 CI	3 601 G93 0R0		
GGS 28 LCE	3 601 B21 100	GWS 13-125 CI	3 601 G9E 000		
GGS 28 LP	3 601 B25 000	GWS 13-125 CIE	3 601 G94 0R0		
GGS 8 CE	3 601 B22 100	GWS 13-125 CIE	3 601 G9F 000		
Дисковая циркулярная пила (GKS)		GWS 13-125 CIEX	3 601 G9F 100	1	
GKS 160	3 601 F70 000, 002	GWS 13-125 CIE	3 601 G9E 100		
GKS 55	3 601 F64 000	GWS 1400	3 601 H24 800, 830, 8R0		
GKS 55	3 601 F64 001	GWS 14-125 C	0 601 704 703, 708, 903		
Штроборез (GNF)		GWS 14-125 CE	0 601 705 703, 708		
GNF 65 A	0 601 368 703, 708	GWS 14-125 CI	3 601 H24 000, 020		
GNF 35 CA	0 601 621 703, 708	GWS 14-125 CIE	3 601 H25 000, 020		
Универсальный резак (GOP)		GWS 14-125 CIT	3 601 H29 000, 020, A00, A30		
GOP 2000 CE	3 601 B30 001	GWS 14-125 INOX	3 601 H29 J00		
GOP 250 CE	3 601 B30 000	GWS 14-125C	0 601 804 503, 508, 573, 574, 703, 708, 773		
GOP 30-28	3 601 B37 000	GWS 14-125CE	0 601 805 503, 508, 573, 574, 703, 708, 773		
Полировальная машина (GPO)		GWS 14-150 C	0 601 706 703	1	
GPO 14 CE	3 601 C89 000	GWS 14-150 CI	3 601 H26 000, 020		
Ударная дрель (GSB)		GWS 14-150C	0 601 806 503, 573, 574		
GSB 16 RE	3 601 A4E 500, 530, 600	GWS 14-150C	0 601 806 703, 708, 732, 773		
GSB 18	0 601 195 003				
GSB 18 RE	0 601 195 703				
GSB 18-2	0 601 185 003				
GSB 18-2 E	0 601 180 703				
GSB 18-2 E	0 601 185 703				
GSB 18-2 RE	3 601 AA2 200				
GSB 18-2 RE	0 601 185 503				
GSB 19-2 RE	3 601 A7B 500, 600				
GSB 19-2 REA	3 601 A7C 500				
GSB 20-2	0 601 19B 003				
GSB 20-2	0 601 184 003				
GSB 20-2 RCE	0 601 19B 703				
GSB 20-2 RCE	0 601 192 703, 708, 770				
GSB 20-2 RE	0 601 19B 403, 503				
GSB 20-2 RE	0 601 194 703, 708, 775, 790, 795				
GWS 15-125 CI	3 601 G95 000				
GWS 15-125 CIE	3 601 G96 000				
GWS 15-125 CIEH	3 601 H30 300, 320, D00				
GWS 15-125 CIEP	3 601 G96 200				
GWS 15-125 CIEX	3 601 G96 100				
GWS 15-125 CIH	3 601 H30 200, 220, C00				
GWS 15-125 CIP	3 601 G95 200				
GWS 15-125 CIPX	3 601 G95 300, 340				
GWS 15-125 CIT	3 601 G97 000				
GWS 15-125 CITH	3 601 H30 400, 420, 700, G00				
GWS 15-125 CIX	3 601 G95 100				
GWS 15-125 Inox	3 601 G9X 000				
GWS 15-150 CI	3 601 G98 000				
GWS 15-150 CIH	3 601 H30 500, 520				
GWS 15-150 CIP	3 601 G98 200				
GWS 17-125 CIE	3 601 G96 0R0				
GWS 17-125 CIE	3 601 G9H 000				
GWS 17-125 CIEX	3 601 G9H 100				
GWS 17-125 CIT	3 601 G97 0R0				
GWS 17-125 CIT	3 601 G9J 000				
GWS 17-125 CIX	3 601 G9G 100				
GWS 17-125 INOX	3 601 G9M 000				
GWS 17-150 CI	3 601 G98 0R0				
GWS 17-150 CI	3 601 G9K 000				
GWS 19-125 CI	3 601 G9N 000				
GWS 19-125 CIE	3 601 G9P 000				
GWS 19-125 CIST	3 601 G9S 000				
GWS 19-150 CI	3 601 G9R 000				
GWS 19-180	0 601 351 103, 108, 803				
GWS 19-230	0 601 352 103, 108, 803				
GWS 20-180	0 601 356 003, 903				
GWS 20-180	0 601 751 003, 008, 013, 020				
GWS 20-180 H	0 601 849 003				
GWS 20-180 H	3 601 H49 L03				
GWS 20-180 J	0 601 751 913				
GWS 20-180 JH	0 601 849 903				
GWS 20-230	0 601 752 003, 008, 013				
GWS 20-230	0 601 850 193				
GWS 20-230 H	0 601 850 003, 065, 103, 108				
GWS 20-230 J	0 601 752 903, 908, 913, 965				
GWS 20-230 JH	0 601 850 903, 908				
GWS 20-230H	3 601 H50 101, 102, L00, L01, L02				
GWS 20-230JH	3 601 H50 M00, M01				
GWS 21-180	0 601 356 103, 803				
GWS 21-180 H	0 601 851 003, 008, 083, 0A3, 0L4				
GWS 21-180 H	3 601 H51 L03				
GWS 21-180 HV	0 601 851 B03, B08				
GWS 21-180 JH	0 601 851 903, 908				
GWS 21-180 JHV	0 601 851 G03, G08, G18				
GWS 21-230	0 601 357 103, 188, 803				
GWS 21-230 H	0 601 852 003, 008, 083, 0A3				
GWS 21-230 H	3 601 H52 L02				
GWS 21-230 HV	0 601 852 B03, B08				
GWS 21-230 JH	0 601 852 903, 908				
GWS 21-230 JHV	0 601 852 G03, G08				
GWS 22-180 H	3 601 H81 100, 101, L00, L01, L02, Y00, Y01				
GWS 22-180 JH	3 601 H81 M00, M01, M02, Z00, Z01				
GWS 22-180 LVI	3 601 H90 D00, D01				
GWS 22-230 H	3 601 H82 100, 101, 190, 191, 193, 1P3, L00, X00, X01, Y00, Y01, Z00				
GWS 22-230 JH	3 601 H82 200, 201, 202, 203, M00, M01, Z01				
GWS 22-230 LVI	3 601 H91 C00, C01, D00, D01				



BOSCH

Разработано для жизни



1	2	3	4	5
1607014176 / 1607031255*	1607014171 / 1607031250	1607000V37 / 1607031266	1617000525 / 1607031256	1607014145 / 1607031223

6	7	8	9	10
1617014126 / 1607031227	1619P02870 / 1607031252	1617014144 / 1607031260	1607000V53 / 1607031254	1617014135 / 1607031236

11	12	13	14	15
2610391290 / 1607031264	3607014010 / 1607031265	2604321941 / 1607031263	1617014143 / 1607031259	2604321905 / 1607031222

*обычный артикул / промо-артикул

GWS 23-180	0 601 753 003	GWS 26-230 JH	3 601 H56 100, 101, 102, 1P1, 1P2, L41, L42, M00, M01, M02	2	GSR 8-6 KE	0 601 426 703	15
GWS 23-180 + SDS	0 601 753 173	GWS 26-230 LVI	3 601 H95 F00, F01, H00, H01		Гайковерт (GDS)		
GWS 23-180 J	0 601 753 873, 878, 903	GWS 580	0 601 376 003, 008		GDS 18 E	0 601 436 808, 803	15
GWS 23-180 JS	0 601 753 973	GWS 600	0 601 375 0VH		Рубанок (GHO)		
GWS 23-180 S	0 601 753 073	GWS 6-115	0 601 375 003, 008, 0V6, 0V7, 903, 908	5	GHO 31-82	0 601 593 003, 103, 166, 168	15
GWS 23-230	0 601 362 003, 903	GWS 6-115 E	0 601 375 503, 703, 708, 7A3, 7A8		Ударная дрель (PSB)		
GWS 23-230	0 601 754 003, 008, 173	GWS 660	0 601 375 065, 0V0		PSB 500 R	0 603 312 803, 808	15
GWS 23-230 J	0 601 754 903, 908	GWS 7-115	0 601 380 003, 073, 103, 903, 948	1	PSB 550 RE	0 603 169 703	
GWS 23-230 JS	0 601 754 973, 978	GWS 7-115	0 601 800 003		PSB 550 RE	3 603 A26 001	
GWS 23-230 S	0 601 754 073, 873, 878	GWS 7-115	3 601 C88 101	7	PSB 500	3 603 A26 000	11
GWS 24-180	0 601 361 103, 803	GWS 7-115 E	3 601 C88 201		PSB 530 RE	3 603 A26 002	
GWS 24-180 B	0 601 853 003	GWS 7-125	3 601 C88 102		PSB 530 RA	3 603 A26 100	
GWS 24-180 H	0 601 853 403, 493, 100	GWS 780 C	0 601 377 7V0	5	PSB 650 RE	3 603 A26 200	
GWS 24-180 JB	0 601 853 903	GWS 8-115	3 601 H20 000, 020, 030	1	PSB 600 RE	3 603 A26 201, 400	
GWS 24-180 JBV	0 601 853 G03, G08	GWS 8-115 C	0 601 377 5V0, 5V1	5	PSB 650 RA	3 603 C85 703	
GWS 24-180 JBX	0 601 863 873	GWS 8-125	3 601 H27 000	1	PSB 550 RA	3 603 C97 400, 402	
GWS 24-180 JH	3 601 H53 M00	GWS 8-125 C	0 601 377 7V2		Рубанок (PHO)		
GWS 24-180 JH	3 601 H83 101, M00, M01	GWS 850 C	0 601 377 7V3	5	PHO 1	0 603 272 203, 208	15
GWS 24-180 LVI	3 601 H92 F00, F01	GWS 850 CE	0 601 378 7V1		PHO 15	0 603 997 989	
GWS 24-230	0 601 362 103, 178, 803, 878	GWS 9-115	3 601 G90 000, 0R0	9	PHO 15-82	0 603 272 103, 160	
GWS 24-230 B	0 601 854 003, 008	GWS 9-115	3 601 G98 000		PHO 20-82	0 603 258 403	
GWS 24-230 BV	0 601 854 B03, B08	GWS 9-115 P	3 601 G90 200	3	PHO 25-82	0 603 296 003	
GWS 24-230 H	0 601 854 403, 408, 493	GWS 9-125	0 601 381 003		PHO 25-83	0 603 296 008	
GWS 24-230 H	3 601 H54 100, L00	GWS 9-125	0 601 701 003, 008, 903	1	PHO 25-91	0 603 296 063	
GWS 24-230 H	3 601 H84 L00, L01	GWS 9-125	0 601 801 003, 008		Ленточная шлифмашина (PBS)		
GWS 24-230 JB	0 601 854 878, 903, 908	GWS 9-125	3 601 G91 000, 0R0	9	PBS 75 A	0 603 270 203	15
GWS 24-230 JBV	0 601 854 G03, G08	GWS 9-125	3 601 G91 200	3	PBS 75 AE	0 603 270 503, 508, 603	
GWS 24-230 JBX	0 601 864 873	GWS 9-125	0 601 381 003		PBS 7 A	0 603 391 003, 008, 080	11
GWS 24-230 JBX	3 601 H64 400, R00, T00	GWS 9-125	0 601 701 003, 008, 903	1	PBS 7 AE	0 603 391 760, 768	
GWS 24-230 JH	0 601 854 503	GWS 9-125	0 601 801 003, 008		PBS 7 A/AE	0 603 391 780	
GWS 24-230 JH	3 601 H54 M00	GWS 9-125	3 601 G91 000, 0R0	9	Эксцентриковая шлифмашина (PEX)		
GWS 24-230 JH	3 601 H84 201, 204	GWS 9-125	3 601 G91 200	3	PEX 11 A	0 603 309 003	15
GWS 24-230 JVX	3 601 H64 500, 501, 502, 505, U00, U07, Z00, Z01, Z02, Z05	Угловая шлифмашина (PWS)			PEX 125 A-1	0 603 283 103, 203, 208	
GWS 24-230 LVI	3 601 H93 F00, F01, H00, H01	PWS 750-115	3 603 A64 000	11	PEX 125 A-2	0 603 283 503	
GWS 24-230JVX	3 601 H64 U01	PWS 750-125	603 A64 100		PEX 125 AE-1	0 603 283 603	
GWS 24-300	0 601 364 003	PWS 750-115	3 603 A64 102		PEX 220 A	3 603 C78 000, 001	11
GWS 24-300 I	0 601 364 903, 973	Лобзик (GST)			Вибрационная шлифмашина (PSS)		
GWS 24-300I	3 601 C64 801	GST 120 BE	0 601 511 603		PSS 28 AE	0 603 285 703	15
GWS 25-180	0 601 755 003, 008, 173	GST 120 E	0 601 510 603		PSS 200 A	3 603 C40 000, 001	
GWS 25-180 J	0 601 755 873, 903	GST 135 BCE	0 601 511 703		PSS 200 AC	3 603 C40 100, 102	
GWS 25-180 JS	0 601 755 973	GST 135 CE	0 601 510 703		PSS 190 AC	3 603 C40 101, 103	11
GWS 25-180 S	0 601 755 073	GST 150 VCE	3 601 E13 000, 001	13	PSS 250 AE	3 603 C40 200	
GWS 25-230	0 601 756 003, 008, 173	GST 150 CE	3 601 E12 000, 001		PSS 300 AE	3 603 C40 300	
GWS 25-230 J	0 601 756 873, 878, 903	GST 600 BE	0 601 511 60A		PSS 280 A	3 603 C40 600	
GWS 25-230 JS	0 601 756 973, 978	GST 600 E	0 601 510 60A		Лобзик (PST)		
GWS 25-230 S	0 601 756 073	GST 90 E	3 601 E8G 000, 001		PST 700 PAE	0 603 303 603, 608, 680	15
GWS 26-180 B	0 601 855 003	Дрель (GBM)			PST 800 PAC	0 603 303 703, 708	
GWS 26-180 BV	0 601 855 B03	GBM 10-2	0 601 168 003		PST 700 PE	3 603 C51 100	
GWS 26-180 H	0 601 855 403, 493	GBM 10-2 RE	0 601 168 503, 560, 568		PST 800 PEL	3 603 C52 100	
GWS 26-180 H	3 601 H55 100	GBM 13 HRE	0 601 023 703		PST 800 PEL	3 603 CA0 100, 101	
GWS 26-180 JB	0 601 855 903	GBM 13 HRE	0 601 049 603, 608		PST 900 PEL	3 603 C53 100	
GWS 26-180 JBV	0 601 855 G03	GBM 13 HRE	3 601 K49 6A0, 6A6	15	PST 900 PEL	3 603 CA0 200	
GWS 26-180 JBV	3 601 H55 U00	GBM 13-2	0 601 169 003, 060		PST 650	3 603 C92 000	
GWS 26-180 JH	3 601 H55 101, 102, M00, M01	GBM 13-2 RE	0 601 169 503, 508, 560, 567		PST 650	3 603 CA0 700	
GWS 26-180 LVI	3 601 H94 F00, F01	GBM 6 E	0 601 135 603, 661		PST 600	3 603 D13 000	11
GWS 26-230 B	0 601 856 003	GBM 6 RE	3 601 D72 600	11	PST 680 E	3 603 C92 100	
GWS 26-230 B	3 601 H56 300, 301, 302	Ленточная шлифмашина (GBS)			PST 650 L	3 603 C92 200	
GWS 26-230 BV	0 601 856 B03	GBS 75 AE	0 601 274 703	15	PST 680 EL	3 603 C92 300	
GWS 26-230 H	0 601 856 403, 493	GBS 75 AE	3 601 B74 7A0		PST 700 E	3 603 CA0 000	
GWS 26-230 JB	0 601 856 903, 908	Шуруповерт (GSR)			PST 7000 E	3 603 CA0 001	
GWS 26-230 JBV	0 601 856 G03, G08	GSR 6-20 TE	0 601 423 703, 760	15	PST 1000 PEL	3 603 CA0 300	
GWS 26-230 JBV	3 601 H56 500, S00, U00	GSR 6-25 TE	0 601 421 703		PST 750 PE	3 603 CA0 301, 500, 501, 502	
GWS 26-230 JH	0 601 856 503	GSR 6-40 TE	0 601 420 703		PST 750 PEL	3 603 CA0 600, 601	
		GSR 8-16 KE	0 601 427 703, 708		PST 670 L	3 603 D13 100	
					PST 700 PEL	3 603 D13 500	